Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: WEST CLARK SECTION 1 CENTRAL FACILITY

Field Name: CLARKS CREEK Well File #:

Date Incident:5/24/2016Time Incident:06:30Facility ID Number:231247-01County:MCKENZIETwp:151Rng:95Sec:1Qtr:SW SW

Location Description:

Submitted By: Danielle Dupay Received By:

Contact Person: Danielle Dupay

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 150 Barrels 150 Barrels 150 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 8/31/2016 Clean Up Concluded: 6/3/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

The leak was stopped and the liquids were removed from the lined containment immediately. The soils inside the lined containment will be removed and when the temp water battery is no longer needed we will remove the liner and remaining material to be disposed of.

Wastes Disposal Location: Liquids were taken to SWD the solids TBD

Agencies Involved: BLM

Updates

Date: 5/27/2016 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location according to the report. NDIC retains oversight.